John Varley House 180 West 500 North Salt Lake City Salt Lake County Utah

HABS No. UT-101

HABS MATH TALKS-81

PHOTOGRAPHS

DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
NATIONAL ARCHITECTURAL AND ENGINEERING RECORD
NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
WASHINGTON, D.C. 20243

Inited States Department of the Interior NATIONAL PARK SERVICE HISTORIC AMERICAN BUILDINGS SURVEY

WASHINGTON, D.C. 20240

ARCHITECTURAL DATA FORM

HARG HATU TSACT81

ΟV.	10110111110 1 O11, D.C. 20210		AKCHITECTORAL D	AIA FUNN	10- 54		
						<u>0-</u>	
ر	STATE	COUNTY		TOWN OR VICINI	TY		
	Utah	Salt La	ke	Salt Lake (City		
i ii Ka	HISTORIC NAME OF STRUCTURE (RCE FOR NAME)	HABS NO.				
	John Varley House (original owner - title records, and city directories)						
	SECONDARY DR COMMON NAMES OF STRUCTURE						
٠.	COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)						
180 West 500 North, Salt Lake City, Utah							
	DATE OF CONSTRUCTION (INCLUDE SOURCE) ARCHITECT(S) (INCLUDE SOURCE)						
		2 00 011027		,			
	C. 1888 (Title records)		Unknown	INAL TICE AL CIDIT	empe)		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)							
	This small single-family dwelling was built c. 1888 for John Varley, a teamster. It located in the "Marmalade" section of the proposed National Register Historic Distriknown as Capital Hill. It is contributory to the District's architectural character						
because of its scale, massing, materials, and vernacular style. STYLE (IF APPROPRIATE)							
	Cottage						
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)							
	tuccoed Adobe with frame additions						
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS DN SEPARATE PAGES ARE ACC Site plan is unusual in turning the narrow, gable end to the street						ABL	
	EXTERIOR FEATURES OF NOTE						
	Plain cornice moulding with partial returns						
The state of the s							
INTERIOR SEATURES OF NOTE (DECORIDE SLOOP DIANS) S NOT SYSTEMS							
	INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Fireplace, interior wood door and window trim						
•							
	MAJOR ALTERATIONS AND ADDITIONS WITH DATES						
	Rear addition - between 1898	•		ndow alteration	.7.6		
	West addition - between 1911 and 1930 Open porch enclosed and altered - date unkn						
	ESENT CONDITION AND USE						
Single-family house is in deteriorated condition and is vacant							
		HER INFORMATION AS APPROPRIATE					
	Documentation for this structure was prepared by Salt Lake City Corporation in compli with Executive Order 11593 and a Memorandum of Agreement with the Advisory Council or						
	Historic Preservation.						
•	SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)						
	Plat records, plat map, Building permits, Sanborn map, City Directories, Obituary						
	index, newspapers.						
COMPILER, AFFILIATION DATE							
				, , , ,	· -		

Dr. Henry Whiteside - Utah State Historical Society Linda Edeiken - Salt Lake City Planning Department

October 14, 198